Parking Recommendations

- 1. Hartley Road/North Road
- 2. Fairmont Street



Fairmont Street entrance to Hartley Park has several issues that need to be addressed

Parking is provided by one, often overfull, parking lot at Hartley Nature Center and on-street parking at neighborhood access areas. Three neighborhood access areas - at Hartley Road, Fairmont Street, and North Road – require improvement. All three require improved wayfinding and interpretive signage.

Hartley Road/North Road Recommendations

At Hartley Road and North Road, the street is narrow, there is no curb and gutter, and there is no turn-around. As a result, on-street parkers face hazards from passing cars as they get in and out of vehicles, have difficulty turning around and sometimes go off the road bed. At

improved parking include:

- » Widen the road within the existing public rightof- way to enable more space for safe on-street parking
- » Add curb and gutter to prevent driving and parking off the road bed
- » Add a no-parking turnaround

Fairmont Street

Fairmont Street is presently underutilized because of severe erosion, severe deterioration of the road bed,

Hartley Road and North Road, recommendations for and illegal dumping. Recommendations to improve Fairmont Street parking include:

- » Widen the road within the existing public rightof- way to enable more space for safe on-street parking
- » Add curb and gutter
- » Add a no-parking turnaround
- » Add rain gardens to direct run-off into the ground rather than into eroded channels and the sewer



